

Salt River Pima-Maricopa Indian Community

10005 East Osborn Road • Scottsdale, Arizona 85256 Phone (480) 362-7700 • Fax (480) 362-5597

MONTHLY PROJECT PROGRESS UPDATE

Project: <u>ECEC Classroom and Parking Expansion</u>

Issued Date: October 4, 2023 | October-2023 UPDATE

Distribution:

	Name	Department/ Company
X	Tami Brungard	ECEC – Edu Leader
X	Lekisha Morris	ECEC
X	Barbara White	ECEC
X	Melody Herne	Act. Superintendent
X	Tate Walker	Public Relations Dir.
X	Deanna Scabby	Edu. Board./ Council
X	Mikah Carlos	Community Council
X	Pamela Prasher	ECEC

	Name	Department/ Company
X	Kimberly Manuel	ECEC – Policy Council
X	Carmen Briones	ECEC – Policy Council
X	Jennifer Correa	ECEC – Policy Council
X	Brittany Barranca	ECEC – Policy Council
X	Frank Perez	ECEC – Policy Council
X	Rene Uriarte	ECEC – Policy Council
X	Symone Kann	ECEC – Policy Council
X	Felicia Toya	ECEC – Policy Council

Work Completed:

Items


- 1. Group #2 Classroom renovation started (A-154, A-139, B-135, C-102). Tentative completion 10/20/23.
- 2. Building B 2nd Floor concrete poured.
- 3. Existing parking lot new light pole install completed.
- 4. Mechanical Yard CMU wall completion.
- 5. Building automation system new cabling installed.


Work anticipated in the next month:

- 1. Group #3 Classroom renovation tentative start end of the month (A-131, A-120, B-142, C-108).
- 2. Building B Addition, mechanical mezzanine level and roof steel decking install. Mechanical mezzanine concrete pour.
- 3. Building B 1st Floor roof membrane install, 2nd Floor Standing seam metal roof start by end of the month.
- 4. On-Going mechanical, plumbing and electrical rough-in work.
- 5. Infant playground area fencing and rubber play surface install.
- 6. Building D Staff Lounge renovation finishes complete by end of month.

SRP-MIC MONTHLY PROJECT PROGRESS UPDATE

Project Schedule | Three Week Look Ahead





SRP-MIC MONTHLY PROJECT PROGRESS UPDATE

Progress Photos:

See attached.







DescriptionPlayground 3 complete.

Taken DateUploaded By09/29/2023 at 02:08 pmCarlos Peralta

Upload Date File Name



Description

Barricade in teachers lounge installed.

 Taken Date
 Uploaded By

 09/29/2023 at 06:30 am
 Carlos Peralta

 Upload Date
 File Name

 09/29/2023 at 03:20 pm
 D8C8B020-8929-47BD-AD15-970...



Description

Playground 3 under Ramp rubber membrane complete.

Taken DateUploaded By09/29/2023 at 02:08 pmCarlos Peralta

Upload Date File Name

09/29/2023 at 03:20 pm CC2E13BD-B627-4907-A5CE-433...




DescriptionRoom A-139 painted


Taken DateUploaded By09/28/2023 at 02:00 pmCameron Vildosola

Upload Date File Name

09/29/2023 at 08:49 am A9C518FF-1DCF-49EA-81C0-0AD...







Description

Ceiling grid patch back complete.

Taken DateUploaded By09/28/2023 at 02:00 pmCameron Vildosola

Upload Date File Name

09/29/2023 at 08:49 am 7EDFD0DD-6150-4693-8407-A5D...



Description


Cleaning holes for pipe stand at mechanical yard for overhead water lines to new chiller.

 Taken Date
 Uploaded By

 09/28/2023 at 01:45 pm
 Carlos Peralta

 Upload Date
 File Name

 09/28/2023 at 01:45 pm
 0AF64F47-6DCD-40DF-9EDC-A60...



Description

Painting at classrooms all complete.

Taken DateUploaded By09/28/2023 at 02:00 pmCameron Vildosola

Upload Date File Name

09/29/2023 at 08:49 am <u>F65455D4-1C04-44</u>61-BE5A-0C9F...



Description

Laundry Room C-110 Drywall repairs in progress.


Taken DateUploaded By09/28/2023 at 12:28 pmCarlos Peralta

Upload Date File Name

09/28/2023 at 01:45 pm 227DA3EF-11E4-4C41-AADE-A1C...








Description

Laundry Room drywall repairs C-103

Taken DateUploaded By09/28/2023 at 12:26 pmCarlos Peralta

Upload Date File Name

09/28/2023 at 01:45 pm 78DF1247-1761-4454-88C8-3754...



Description

Steel for east stairwell storefront

Taken Date

Uploaded By


09/28/2023 at 12:16 pm

Carlos Peralta

Upload Date

File Name

09/28/2023 at 12:23 pm 6A03F2C0-7D78-4454-87AF-3AB...



Description

New barricades deliver and installed.

Taken DateUploaded By09/28/2023 at 12:24 pmCarlos Peralta

Upload Date File Name

09/28/2023 at 01:44 pm 9B618974-4251-4B26-A0A4-09D...




Description

Light poles assembly complete for ECEC


Taken DateUploaded By09/28/2023 at 12:15 pmCarlos Peralta

Upload Date File Name

09/28/2023 at 12:23 pm 0E5834AE-31A6-4139-9060-F599...








Description

Second floor concrete complete

Taken DateUploaded By09/28/2023 at 07:58 amCarlos Peralta

Upload Date File Name



Description

New light poles install and energize in progress.

Taken Date

Uploaded By


09/28/2023 at 05:54 am

Carlos Peralta

Upload Date

File Name

09/28/2023 at 07:09 am B48DCEE4-F73E-4770-85BA-B8F8...




Description

Bus drop off lighting complete and energize.

Taken DateUploaded By09/28/2023 at 05:54 amCarlos Peralta

Upload Date File Name

09/28/2023 at 07:09 am D068ADC9-966A-4C76-9D24-09A...



Description

Heat pumps at bldg. B install in progress.

Taken DateUploaded By09/27/2023 at 02:44 pmCarlos Peralta

Upload Date File Name

09/27/2023 at 02:55 pm 47848358-6F8F-4667-B979-184F...







Description

Texture complete at all classroom renovation.

Taken DateUploaded By09/27/2023 at 11:09 amCarlos Peralta

Upload Date File Name09/27/2023 at 11:59 am
9A4081B0-DEF8-40C6-A847-



Description


Split face block repairs complete.

 Taken Date
 Uploaded By

 09/27/2023 at 09:29 am
 Carlos Peralta

 Upload Date
 File Name

 09/27/2023 at 11:53 am
 F151FF5D-B638-401B-833F-BE58...




Description

Ceiling grid repairs all complete at all classrooms renovation

Taken DateUploaded By09/27/2023 at 11:09 amCarlos Peralta

Upload Date File Name

09/27/2023 at 11:58 am D50C356D-58ED-4495-90F9-A74...




Description

Steel hade install complete South side.


Taken DateUploaded By09/27/2023 at 06:22 amCarlos Peralta

Upload Date File Name

09/27/2023 at 08:52 am CECA53C1-23E8-4E46-AB79-F25...







Description

Second floor concrete pour in progress bldg.B

Taken DateUploaded By
09/27/2023 at 04:39 am
Carlos Peralta

Upload Date File Name09/27/2023 at 05:08 am D480DB68-8DDB-4D15-987B-



Description

Bum extended ready for pumping.

 Taken Date
 Uploaded By

 09/27/2023 at 04:36 am
 Carlos Peralta

 Upload Date
 File Name

 09/27/2023 at 05:04 am
 443C5CF7-86A6-431C-ACEC-2CB...



Description

Concrete pump ready for concrete pour.

Taken DateUploaded By
09/27/2023 at 04:36 am
Carlos Peralta

Upload Date File Name

09/27/2023 at 05:02 am B5762F8E-E8A7-4856-B68E-E485...




Description

Taken DateUploaded By09/26/2023 at 12:40 pmCarlos Peralta

Upload Date File Name

09/26/2023 at 12:41 pm 61427935-7DDC-4BD3-A3BC-C76...








Description

Light poles heads install in progress.

Taken Date Uploaded By 09/25/2023 at 11:23 am Carlos Peralta

Upload Date File Name



Description

Description Light poles delivery

Taken Date Uploaded By 09/25/2023 at 09:03 am Carlos Peralta

Upload Date File Name

09/25/2023 at 09:31 am 5129F377-119E-4359-9316-7F92...



Description

Taken Date 09/22/2023 at 02:16 pm

Upload Date File Name

09/22/2023 at 02:31 pm E045AFA4-12E7-4CFD-95E1-DF2F...

Uploaded By

Carlos Peralta

Taken Date

09/22/2023 at 02:15 pm


Upload Date 09/22/2023 at 02:31 pm **Uploaded By** Carlos Peralta

File Name

8AF3E875-BF53-4A99-B62E-5826...







Description

Canopy columns on the north side.

Taken DateUploaded By09/22/2023 at 12:49 pmCarlos Peralta

 Upload Date
 File Name


 09/22/2023 at 12:49 pm
 D14B34CC-5006-49F6-9C9D-0E3...

Description

Duct install complete Classroom A 139

Taken Date Uploaded By
09/22/2023 at 12:44 pm Carlos Peralta
Upload Date File Name

09/22/2023 at 12:48 pm DC387CE1-66D1-47FA-9095-2F77...



Description

Bldg. B Overhead MPE in progress.

Taken DateUploaded By09/22/2023 at 12:48 pmCarlos Peralta

Upload Date File Name




Description

Painting protection installs in progress in all classrooms.

Taken DateUploaded By09/22/2023 at 12:43 pmCarlos Peralta

Upload Date File Name

09/22/2023 at 12:48 pm BE780AF8-7103-4246-9D0B-078...








Description

Upload Date

Canopy columns on the south side.

Taken DateUploaded By09/22/2023 at 12:42 pmCarlos Peralta



File Name

Description


Second walk thru, tours the east

 Taken Date
 Uploaded By

 09/22/2023 at 12:39 pm
 Carlos Peralta

 Upload Date
 File Name

 09/22/2023 at 12:41 pm
 9266CD0E-CD3C-4ECC-9E51-2E8...



Description

Bent plate install complete at duct shaft on second floor.

Taken DateUploaded By09/22/2023 at 12:40 pmCarlos Peralta

Upload Date File Name

09/22/2023 at 12:41 pm 769A406E-CDD7-4B72-8711-628...



Description

Rebar on the north to tie in floor to stair landing.

Taken DateUploaded By09/22/2023 at 12:39 pmCarlos Peralta

Upload Date File Name

09/22/2023 at 12:41 pm 837A83C2-D2C0-415E-AB40-1BC...







Description

concrete band install 2nd section

Taken DateUploaded By09/21/2023 at 04:46 amCameron Vildosola

Upload Date File Name

09/21/2023 at 05:25 am 0A32A14B-AA03-411D-8B1F-3C2...



Description

Above ceiling valves copper fittings install ready for heat pump connection.

Taken DateUploaded By09/20/2023 at 11:30 amCarlos Peralta

Upload Date File Name

09/20/2023 at 11:42 am A87DF189-F550-4656-9DE0-568...



Description

concrete band install 1st section

Taken DateUploaded By09/21/2023 at 04:45 amCameron Vildosola

Upload Date File Name

09/21/2023 at 05:25 am 8F9219A3-F201-4EB5-AADF-2F44...



Description

column install southeast side

Taken DateUploaded By09/20/2023 at 09:00 amCameron Vildosola

Upload Date File Name

09/25/2023 at 08:13 am 61A8B5E0-C327-42CE-9BBC-41D...







Description

Canopy columns install in progress.

Taken Date 09/20/2023 at 08:07 am


Upload Date

09/20/2023 at 08:51 am

Uploaded By Carlos Peralta

File Name

781CE054<u>-4A8F-41</u>F4-8A09-25ED...



Description

wire mesh install

Taken Date 09/20/2023 at 07:28 am

Upload Date


09/21/2023 at 07:25 am

Uploaded By

Cameron Vildosola

File Name

635C4A90-8501-4B87-9C37-3B9...



Description

Ninyo and moore

Taken Date

09/20/2023 at 07:30 am

Upload Date


09/20/2023 at 08:51 am

Uploaded By

Carlos Peralta

File Name

B082A397-0<u>467-47</u>68-9E9B-14E6...



Description

Nelson studs passing inspection

Taken Date

09/20/2023 at 07:28 am

Upload Date

09/25/2023 at 08:13 am

Uploaded By

Cameron Vildosola

File Name

6B20A67F-8B71-4665-9AA2-67E...








DescriptionBent plate delivery.

Taken DateUploaded By
09/19/2023 at 09:56 am
Carlos Peralta

Upload Date File Name



Description

Description

Curve Metal Panels on site.

Taken DateUploaded By09/19/2023 at 09:56 amCarlos Peralta

Upload Date File Name

09/19/2023 at 10:05 am 4366B4DA-244B-40F3-A759-63A...




Description

Sampling station Complete.

Taken DateUploaded ByTaken DateUploaded By09/19/2023 at 09:22 amCarlos Peralta09/19/2023 at 09:16 amCarlos Peralta

Upload Date File Name Upload Date File Name

 $09/19/2023 \text{ at } 10:04 \text{ am} \\ 5B805930-645F-4477-82DC-88E1... \\ 09/19/2023 \text{ at } 09:17 \text{ am} \\ 9701ABA2-9128-44F6-BF96-5BF5... \\ 09/19/2023 \text{ at } 09:17 \text{ am} \\ 09/19/2023 \text{ at } 09:17 \text{ at } 09:$








Description

Nelson studs welding in progress.

Taken Date Uploaded By 09/19/2023 at 07:08 am Carlos Peralta

Upload Date File Name

09/19/2023 at 09:16 am 7CAFA9C9-8B74-49C6-A840-A44...



Description

Upload Date

Infant area fence post install complete.

Taken Date Uploaded By 09/15/2023 at 10:12 am Carlos Peralta

09/15/2023 at 10:23 am 1EB55CBC-335B-418A-A261-49C...

File Name




Description

Forming for concrete Ban in progress at infant area.

Taken Date Uploaded By 09/18/2023 at 11:12 am Carlos Peralta

Upload Date File Name

BFD1CD5C-2679-4D63-922B-3D6... 09/18/2023 at 11:46 am



Description

Second floor decking install in progress.


Taken Date Uploaded By 09/15/2023 at 09:37 am Carlos Peralta

Upload Date File Name

09/15/2023 at 10:16 am DC9FBC3E-16BA-476B-969B-34C...







Description


Upload Date

Decking welding in progress.

Taken DateUploaded By09/15/2023 at 09:37 amCarlos Peralta

09/15/2023 at 10:12 am 94F75833-D5F2-475C-8D86-444F...

File Name




Description

09/14/2023 at 02:05 pm

Installed fence post between laundry rooms

Taken Date Uploaded By
09/14/2023 at 01:15 pm Cameron Vildosola
Upload Date File Name

B64FA031-AC4D-416A-BCF7-F149...



Description

Fence post installed left of laundry ramp

Taken DateUploaded By09/14/2023 at 01:15 pmCameron Vildosola

Upload Date File Name




Description

APS heat pump plumbing install in progress

Taken DateUploaded By09/14/2023 at 08:31 amCarlos Peralta

Upload Date File Name

09/14/2023 at 08:58 am 7776070A-3018-41B0-8ADE-2EB...








Description

Decking install in progress

Taken Date Uploaded By 09/14/2023 at 08:30 am Carlos Peralta


Upload Date File Name



Description

Blank plate ceiling tile half-demoed in A-139

Taken Date Uploaded By 09/14/2023 at 07:24 am Cameron Vildosola **Upload Date File Name** 09/14/2023 at 07:32 am B8D6EAC7-1646-4CE0-BAE8-11E...



Description

A-139 ceiling tile demo, back right corner

Taken Date Uploaded By 09/14/2023 at 07:24 am Cameron Vildosola

Upload Date File Name

09/14/2023 at 07:32 am 65438D14-3B50-4B38-8474-EE7...




Description

Diffuser set on ceiling grid in A-139


Taken Date Uploaded By 09/14/2023 at 07:24 am Cameron Vildosola

Upload Date File Name

27F35485-EE1D-4CC3-BFB7-75A... 09/14/2023 at 07:33 am







Description


Upload Date

Floor protection A-139

Taken DateUploaded By09/14/2023 at 07:24 amCameron Vildosola

09/14/2023 at 07:32 am 89A5B296-13F7-49EF-BF93-FBE6...

File Name



Description

Floor protection A-139 with vent filter on the floor

Taken DateUploaded By09/14/2023 at 07:24 amCameron Vildosola




Description

Floor protection A-139

Taken DateUploaded By09/14/2023 at 07:24 amCameron Vildosola

Upload Date File Name

09/14/2023 at 07:33 am EFF4BF95-5C4D-41C9-AE62-DBE...




Description

Floor protection and ceiling tile delivery in A-139


Taken DateUploaded By09/14/2023 at 07:21 amCameron Vildosola

Upload Date File Name

09/14/2023 at 07:45 am A80A2121-22FE-46F5-AC53-BF79...







Uploaded By

File Name

Description

Upload Date

Projector covering in A-154

Taken Date 09/14/2023 at 07:21 am

09/14/2023 at 07:49 am

/14/2023 at 07:21 am Cameron Vildosola

198731E4-D032-4FC7-B610-7F8A...



Description

Ceiling tile demo B-135


Taken Date 09/14/2023 at 07:17 am

Upload Date 09/14/2023 at 08:27 am

Uploaded ByCameron Vildosola

File Name

2C32F411-0EA0-441E-886C-7069...



Description

Demo ceiling tile in A-154

Taken DateUploaded By09/14/2023 at 07:21 amCameron Vildosola

Upload Date File Name

09/14/2023 at 07:49 am 296B7B0D-8ADA-45AA-98C4-757...



Description

Connected vent filters in B-135


Taken DateUploaded By09/14/2023 at 07:17 amCameron Vildosola

Upload Date File Name

09/14/2023 at 08:27 am 2A4F342B-4134-4208-A999-9C4F...







Description

Floor protection in B-135

Taken Date 09/14/2023 at 07:17 am


Upload Date

09/14/2023 at 08:27 am

Uploaded ByCameron Vildosola

File Name

AC8B7C7E-88F0-4ACE-B81A-44C...



Description

Taken Date 09/13/2023 at 12:10 pm

Upload Date


09/14/2023 at 08:27 am

Uploaded By

Cameron Vildosola

File Name

10A57670-A7BA-436C-A1EC-488...



Description

Floor protection and ceiling tile delivery in B-135

Taken Date

09/14/2023 at 07:17 am

Upload Date

09/14/2023 at 08:27 am

Uploaded By

Cameron Vildosola

File Name

C5BD154E-0CAE-495E-A24B-E94...



Description

Infant area fence post holes.

Taken Date

09/12/2023 at 08:01 am

Upload Date

09/12/2023 at 08:17 am

Uploaded By

Cameron Vildosola

File Name

41A78F29-A8C7-4ACF-B43B-865E...







Uploaded By

File Name

Cameron Vildosola


Description

Infant area fence post holes.

Taken Date 09/12/2023 at 08:01 am

Upload Date

09/12/2023 at 08:20 am



Description

Floor protection in place.

Taken Date 09/11/2023 at 01:35 pm

Upload Date 09/11/2023 at 02:05 pm **Uploaded By** Carlos Peralta

File Name 5030A6FD-CE62-449E-8224-E821...



Description

Floor protection in place.

Taken Date Uploaded By 09/11/2023 at 01:35 pm Carlos Peralta

Upload Date File Name

09/11/2023 at 06:53 pm 6E07F7E7-9D28-4D12-9E1A-BD4...




Description

Cricket at existing building framed and rock wood to follow.


Taken Date Uploaded By 09/11/2023 at 07:42 am Carlos Peralta

Upload Date File Name

09/11/2023 at 07:45 am 5116C6E0-FD4A-4F8E-9112-F2B3...









Uploaded ByCarlos Peralta

Upload Date File Name

Taken Date

Taken Date

09/08/2023 at 10:47 am

09/08/2023 at 01:38 pm

09/08/2023 at 02:12 pm 9F18617D-5968-44E1-BFF3-6E13...



Description

Uploaded By Carlos Peralta

Upload Date File Name09/08/2023 at 10:53 am 7ECA0E4E-7800-4A02-90C2-8678...



Description

Taken DateUploaded By09/08/2023 at 01:38 pmCarlos Peralta

Upload Date File Name

09/08/2023 at 02:12 pm AB954E0D-0A06-46D4-A573-B25...



Description

Taken DateUploaded By09/08/2023 at 10:47 amCarlos Peralta

Upload Date File Name

09/08/2023 at 10:53 am 27F3AC7C-970A-48AE-9D09-6C6...







Description

Aerial view Mechanical Yard.

Taken DateUploaded By09/07/2023 at 01:41 pmSaen Framjee

Upload Date File Name

09/12/2023 at 10:29 am 50C2C651-2A38-423E-AAFF-290E...



Description

Aerial view bldg.B

Taken DateUploaded By09/07/2023 at 01:40 pmSaen Framjee

Upload Date File Name

09/12/2023 at 10:29 am 59D8D89A-87F2-44E2-8907-2FD...



Description

Aerial view bldg.B

Taken DateUploaded By09/07/2023 at 01:40 pmSaen Framjee

Upload Date File Name

09/12/2023 at 10:29 am C28EEE4E-41AE-484D-8EA4-440...



Description

Aerial view bldg.B

Taken DateUploaded By09/07/2023 at 01:38 pmSaen Framjee

Upload Date File Name

09/12/2023 at 10:29 am 55955519-7339-466F-B732-AB64...







DescriptionAerial view bldg.B

Taken DateUploaded By09/07/2023 at 01:37 pmSaen Framjee

Upload Date File Name

09/12/2023 at 10:29 am 106887F5-C49F-4675-9D27-C1D...



DescriptionAerial view bldg.B

Taken Date
Uploaded By
09/07/2023 at 01:36 pm
Saen Framjee
Upload Date
File Name

09/12/2023 at 10:29 am 7CABD274-E327-4746-B00E-77C...



DescriptionAerial view bldg.B

Taken DateUploaded By
09/07/2023 at 01:37 pm
Saen Framjee

Upload Date File Name



Description


Taken DateUploaded By09/07/2023 at 07:53 amCarlos Peralta

Upload Date File Name

09/07/2023 at 08:23 am D5FD7219-B1CD-45D6-9264-604...







Description

Taken Date

Upload Date

09/06/2023 at 03:18 pm

Uploaded ByCarlos Peralta

File Name

09/06/2023 at 08:30 pm CBEA7219-F59F-4793-A69F-A452...



Description


Taken Date

09/06/2023 at 03:17 pm

Uploaded ByCarlos Peralta

Upload Date File Name

09/06/2023 at 08:30 pm 2A289704-DB68-4240-AEA6-E3C...



Description

Taken DateUploaded By09/06/2023 at 03:17 pmCarlos Peralta

Upload Date File Name

09/06/2023 at 08:30 pm F0E8BDDA-63D5-48A9-BA9A-5B6...



DescriptionW&W Crane on site.


Taken DateUploaded By09/06/2023 at 08:29 amCarlos Peralta

Upload Date File Name

09/06/2023 at 03:04 pm 0B69D79B-0E9D-429C-B812-A13...



Job #: 22-2-010 ECEC Classroom (Precon) 4815 N. Center St. Scottsdale, Arizona 85256



Description

Mechanical yard top out ready for grout.

Taken DateUploaded By09/06/2023 at 08:29 amCarlos Peralta

Upload Date File Name

09/06/2023 at 03:04 pm DAA7B63F-6E8E-43A9-942A-DEE...

SRP-MIC MONTHLY PROJECT PROGRESS UPDATE

Attachments:

Item/s

1. None